



## **GACOBOND™ BIG STICKY LVOC MULTI-PURPOSE ADHESIVE**

### **A. DESCRIPTION:**

GacoBond™ Big Sticky LVOC is an aerosol canister adhesive designed with tenacious grab tack and a long open time. GacoBond Big Sticky LVOC can be used for most temporary or light duty, low stress bonding applications such as bonding insulation batting to interior wall cavities, and adhering VCT (Vinyl Composition Tile) to wood. GacoBond Big Sticky LVOC produces an adjustable web spray pattern for controlled dispersion and 100% transfer efficiency of adhesive to substrate.

### **B. ADVANTAGE:**

- Exceptional Grab Tack
- Quick Dry Time
- Very Long Working Time
- Excellent adhesion to many substrates
- Multipurpose Applications
- Good Spray Pattern
- Excellent Coverage
- High Green Strength
- Excellent Heat Resistance

### **C. TYPICAL USES:**

- Labeling
- Most Plastics
- VCT
- Glasswork
- Upholstery
- Felt/ Fabrics
- Dust Liner and Wrap
- Fiberglass Insulation
- Paper Products
- Urethane Foams

### **D. APPROVED EQUIPMENT:**

- Spray gun: SG200
- Spray Tip: ST6501
- Hose: MH973 (12')

### **E. PACKAGING:**

- 30lbs Canister
- 140lbs Canister
- 300lbs Canister

**F. PACKAGED PRODUCT DATA<sup>1</sup>:**

<b>PROPERTY</b>	<b>DESCRIPTION</b>
<b>BASE</b>	Synthetic Polymer
<b>SOLVENT</b>	Organic Solvent *
<b>WEIGHT/GALLON</b>	7.89 lbs. / gallon
<b>COLOR</b>	Clear
<b>FLASHPOINT</b>	8.6°F (-13°C)
<b>STORAGE STABILITY</b>	** The shelf life for an unopened container of this adhesive stored at temperatures between 60°F (15.6°C) and 95°F (35°C) is 1 year from date of manufacture. Store out of direct sunlight in a cool, well-ventilated area. Avoid storing container directly on the floor or against an outside wall.
<b>TOXICITY</b>	Reports have associated repeated and prolonged occupational exposure to solvents with permanent brain and nervous system damage.
<b>V.O.C.<sup>4</sup></b>	44.1 gr/L (EPA Method 24)
<b>FORMALDEHYDE</b>	No urea formaldehyde added during adhesive Manufacturing.
<b>OPEN TIME</b>	60 Minutes
<b>DRY TIME</b>	2-5 Minutes

**G. APPLICATION:**

- Use only after careful consideration of the warnings, directions, and first aid instructions given. Do not thin.
- Surfaces to be bonded should be clean, dry, and free of any dust, loose paint, wax, moisture, dirt, grease, oil, rust, or other contaminants.
- Before initial use securely attach gun to hose, then hose to canister. Fully open canister valve; do NOT close valve until empty.
- Adhesive should be at 60°F (15.6°C) to 95°F (35°C). For best results, adhesive and materials to be bonded should be 60°F (15.6°C) to 95°F (35°C) during application.
- Allow substrates to acclimate to room temperature for 48 hours before bonding.
- Spraying from 8 to 12 inches away, apply adhesive uniformly to both surfaces and cover each surface a minimum of 80%. Some porous surfaces may require two coats. 100% coverage is recommended for the edges. Use only approved equipment.
- For typical applications, a coating weight of 2.5 dry grams per square foot is recommended.
- Both surfaces must be allowed to dry before bonding. This will usually take from 2 to 5 minutes at room temperature under normal conditions. Heat and humidity, or cold weather can affect drying times. Surfaces are dry if adhesive is tacky, but no adhesive transfers to the hand when touched.
- Complete the bond within 60 minutes (under normal conditions) after the adhesive is dry. If the two surfaces do not grab immediately when brought into contact, they have dried too long.
- Position coated surface carefully before putting them together since no shifting is possible once contact is made.
- Bring surfaces together and immediately apply firm pressure (30 psi) over entire surface working from the center to the edges.
- Let bonded parts cure for at least 72 hours before exposing to direct sunlight of temperatures over 150° F (65.6°C).
- Do not use on some vinyls or polystyrene foam. Some vinyls contain plasticizers, which can, over time, soften and dissolve the bond, or bleed through/dicolor. When in doubt, or if product is to be used on vinyls, or other light-colored materials, conduct compatibility testing on the product to be bonded before use.
- After initial assembly, leave the hose and gun attached to the canister with the valve open.
- After safely releasing line pressure, detach gun and hose only when transferring to a new canister.
- Reattach gun and hose immediately.

**H. ATTENTION:**

- Empty container remains hazardous until all flammable vapors, which may explode upon ignition, are gone from residue and container. Observe all labeled hazard precautions. Do not cut, puncture, or weld while hazard exists.
- Do not reuse empty container. Recycle, or dispose of, according to all federal, state, and local regulations.

*<sup>1</sup> For specific Health and Safety information please refer to applicable Safety Data Sheet (SDS)*

***CLEAN UP:***

*Equipment and tools should be cleaned immediately after use with acetone or other exempt solvent.*